




PT=+0,20



2000

A

PT=UT=-0,20

PT=+0,15

30

10500

20

st.15/1



PT=+0,05

36

PT=-0

PT=-0,13

PT=-0,10

1385

600

PT=+0,13

9

3950

5125


3

PT=-0,82

5645

23

PT=+0,13



PT=-0,82

38

33

13

3270

PT=-0,58

17055

2

A

PT=-0,70

8730

PT=+0,08

6300

10500

PT=-0,17

1

4205

13

PT=-0,39

2

PT=-0,58

PT=-0,82

2950

10

1500

29

